[Fig. 7]

A: Thickness (mm) of large diameter portion

B: Diameter (mm) of large diameter portion

[Fig. 8]

A: Pin strength

B: Average

C: Standard deviation

D: Results of measurement

[Fig. 9]

A: Mode of destruction

B: Pin break

C: Board destruction

D: Solder destruction